9505 Santa Paula Drive
Fort Worth, Texas 76116
Phone: 817-244-6212
Fax: 817-244-4024
Tech: 800-423-9696
E-Mail: painless@airmail.net
WebSite:http://www.painlesswiring.com

SERVICE BULLETIN

Wh-365

60502/ 60505 `94-95 LT1 HARNESS DLC CONNECTOR MODIFICATION

This service bulletin pertains to the DLC connector originally installed on the 60502 and 60505 harness. When scanner connector requires the 1994 model 12 pin connector the following steps are necessary to convert from the 1995 16 pin connector that comes installed on the harness.

1. Remove the DLC connector from the mounting bracket.

2. Cut the wires going to the DLC connector to match the length needed to reconnect the new DLC connector.

3. Install new DLC connector in existing bracket.

4. Match wires color to color and connect with butt connectors supplied.

5. Two wires will not be used, the orange wire and the black wire. These wires are to be taped and stowed out of the way.

If you have any questions or need assistance give us a call at 1-800-423-9696 or email us at www.painlessperformance.com.

01-25-02